



CESA: 05 *Number of schools reported for CESA 05: 136*

Which best describes the location of your school building?

0	0.00%	<i>Large Central City (Population greater than 400,000 and density greater than 6,000.)</i>
0	0.00%	<i>Mid-Size Central City (Population less than 400,000 and density less than 6,000.)</i>
0	0.00%	<i>Urban Fringe of Large City (Defined as urban by the Census Bureau.)</i>
0	0.00%	<i>Urban Fringe of Mid-Size City (Defined as urban by the Census Bureau.)</i>
0	0.00%	<i>Large Town (Population greater than or equal to 25,000.)</i>
62	45.59%	<i>Small Town (Population less than 25,000 and greater than or equal to 2,500.)</i>
74	54.41%	<i>Rural (Population less than 2,500 and coded rural by the Census Bureau.)</i>

A. PHYSICAL STRUCTURE AND MECHANICAL FEATURES

4. *When was the school originally constructed?*

<i>Pre-1900</i>	1	0.74%	<i>1930-1939</i>	9	6.62%	<i>1970-1979</i>	14	10.29%
<i>1900-1909</i>	0	0.00%	<i>1940-1949</i>	4	2.94%	<i>1980-1989</i>	3	2.21%
<i>1910-1919</i>	1	0.74%	<i>1950-1959</i>	41	30.15%	<i>1990-1999</i>	23	16.91%
<i>1920-1929</i>	6	4.41%	<i>1960-1969</i>	34	25.00%			

5. *In your opinion, is this school building overcrowded?*

Yes	36	26.47%	No	100	73.53%
-----	----	---------------	----	-----	---------------

6. *If the original building has been renovated or had additions, when was the most recent, MAJOR renovation or addition?*

<i>No Renovation</i>	45	33.09%	<i>1940-1949</i>	0	0.00%	<i>1970-1979</i>	6	4.41%
<i>Before 1930</i>	0	0.00%	<i>1950-1959</i>	1	0.74%	<i>1980-1989</i>	13	9.56%
<i>1930-1939</i>	0	0.00%	<i>1960-1969</i>	6	4.41%	<i>1990-1999</i>	65	47.79%

7. *How many total square feet does the original building have?*

<i>Minimum:</i>	1,680	<i>Maximum:</i>	278,000	<i>Median:</i>	32,102	<i>Average:</i>	54,880
-----------------	-------	-----------------	---------	----------------	--------	-----------------	--------

8. *If the building has been renovated or added on to, how many total square feet exist now?*

<i>Minimum:</i>	5,888	<i>Maximum:</i>	292,766	<i>Median:</i>	54,485	<i>Average:</i>	69,887
-----------------	-------	-----------------	---------	----------------	--------	-----------------	--------

9. *How many portable classrooms were in use during the 1998-99 school year?*

Number of schools reporting the use of portable classrooms: 12

<i>Minimum:</i>	1	<i>Maximum:</i>	39	<i>Median:</i>	1	<i>Average:</i>	4
-----------------	---	-----------------	----	----------------	---	-----------------	---

10. *Does the school accommodate any of its students in instructional facilities located OFF-SITE?*

Yes	3	2.21%	No	133	97.79%
-----	---	--------------	----	-----	---------------

11. *How many of this school's FTE students are located in OFF-SITE facilities?*

Number of schools reporting OFF-SITE facilities: 3

<i>Minimum:</i>	2	<i>Maximum:</i>	200	<i>Median:</i>	3	<i>Average:</i>	68
-----------------	---	-----------------	-----	----------------	---	-----------------	----

CESA: 05 *Number of schools reported for CESA 05: 136*

Definitions for questions #12 and #15:

- Excellent:** New or easily restorable to "like new" only minimal routine maintenance.
- Good:** Only routine maintenance or minor repair required.
- Adequate:** Some preventive maintenance and/or corrective repair required.
- Fair:** Fails to meet code and functional requirement in some cases; extensive repair.
- Poor:** Consistent substandard performance; major corrective repair or overhaul.
- Replace:** Non-operational or significantly substandard performance. Replacement
- NA:** Not Applicable

12. *What is the overall condition of the original buildings and the permanent additions?*

	<i>Excellent</i>	<i>Good</i>	<i>Adequate</i>	<i>Fair</i>	<i>Poor</i>	<i>Replace</i>	<i>NA</i>
<i>Original Buildings:</i>	25 18.38%	46 33.82%	50 36.76%	11 8.09%	2 1.47%	0 0.00%	2 1.47%
<i>Permanent Additions:</i>	32 23.53%	38 27.94%	30 22.06%	2 1.47%	0 0.00%	0 0.00%	34 25.00%

13. *What would be the total cost of all repairs/renovations/modernizations required to put this school's ON-SITE buildings in good overall condition?* *Number of schools reporting cost for repairs/renovations/modernizations: 63*

CESA Total Costs = \$92,913,654

Minimum: \$10,000 *Maximum:* \$27,676,000 *Median:* \$400,000 *Average:* \$1,474,820

14. *On which of the sources listed below is this estimate based? Choose all that apply.*

- 67 **36.41%** *Does not apply--already in good (or better) overall condition.*
- 34 **18.48%** *Facilities inspection/assessment performed within the last three years by licensed professionals.*
- 3 **1.63%** *Repair/renovation/modernization work already being performed/contracted for.*
- 18 **9.78%** *Capital improvement/facilities master plan or schedule.*
- 43 **23.37%** *My best professional judgement.*
- 19 **10.33%** *Opinions of others.*

15. *Overall, what is the physical condition of each of the building features listed below for this school's ON-SITE buildings?*

	<i>Excellent</i>	<i>Good</i>	<i>Adequate</i>	<i>Fair</i>	<i>Poor</i>	<i>Replace</i>
<i>Roofs:</i>	36 26.47%	62 45.59%	32 23.53%	5 3.68%	1 0.74%	0 0.00%
<i>Framing, floors, foundations:</i>	35 25.74%	64 47.06%	26 19.12%	10 7.35%	1 0.74%	0 0.00%
<i>Exterior walls, finishes, windows, doors:</i>	26 19.12%	55 40.44%	43 31.62%	7 5.15%	3 2.21%	2 1.47%
<i>Interior finishes, trims:</i>	23 16.91%	66 48.53%	43 31.62%	2 1.47%	2 1.47%	0 0.00%
<i>Plumbing:</i>	18 13.24%	60 44.12%	43 31.62%	12 8.82%	3 2.21%	0 0.00%
<i>Heating ventilation, air conditioning:</i>	20 14.71%	51 37.50%	45 33.09%	14 10.29%	4 2.94%	2 1.47%
<i>Electrical power:</i>	30 22.06%	58 42.65%	35 25.74%	10 7.35%	3 2.21%	0 0.00%
<i>Electrical lighting:</i>	29 21.32%	64 47.06%	31 22.79%	11 8.09%	1 0.74%	0 0.00%
<i>Life safety requirements (e.g., emergency lighting and warning systems, exit signs):</i>	40 29.41%	63 46.32%	19 13.97%	10 7.35%	1 0.74%	3 2.21%

CESA: 05 *Number of schools reported for CESA 05: 136*

16. *How adequate is your current maintenance budget for keeping your buildings in good overall condition?*

Very Adequate:	6	4.41%	Somewhat Adequate:	61	44.85%
Adequate:	61	44.85%	Not adequate at all:	8	5.88%

17. *How satisfactory or unsatisfactory is each of the following environmental factors in this school's ON-SITE buildings?*

	Very Satisfactory	Satisfactory	Unsatisfactory	Very Unsatisfactory
Lighting:	33 24.26%	98 72.06%	5 3.68%	0 0.00%
Heating:	20 14.71%	100 73.53%	14 10.29%	0 1.47%
Ventilation:	16 11.76%	97 71.32%	21 15.44%	2 1.47%
Indoor air quality:	21 15.44%	99 72.79%	15 11.03%	1 0.74%
Acoustics for noise control:	20 14.71%	94 69.12%	21 15.44%	1 0.74%
Flexibility of instructional space:	19 13.97%	81 59.56%	34 25.00%	2 1.47%
Energy efficiency/conservation:	22 16.18%	88 64.71%	23 16.91%	3 2.21%
Physical security of buildings:	25 18.38%	98 72.06%	10 7.35%	3 2.21%
Exterior noise:	40 29.41%	93 68.38%	2 1.47%	1 0.74%

18. *How many instructional classrooms were in use as of the third Friday in September, 1998?*

Total number of instructional classrooms reported in use as of the third Friday in September, 1998: **3,561**

Minimum:	1	Maximum:	88	Median:	23	Average:	26
----------	---	----------	----	---------	----	----------	----

19. *Does the school building have CENTRAL air conditioning (cools all interior space)?*

Yes	35	25.74%	No	101	74.26%
-----	----	---------------	----	-----	---------------

20. *Does this school have air conditioning in instructional classrooms, computer labs, and/or the library?*

30	29.41%	Yes, in instructional classrooms.
35	34.31%	Yes, in computer labs.
37	36.27%	Yes, in the library.

21. *How many instructional classrooms have air conditioning?*

Minimum:	1	Maximum:	35	Median:	7	Average:	8
----------	---	----------	----	---------	---	----------	---

22. *Does this school have a separate room for a library/resource/media center?*

Yes	128	94.12%	No	8	5.88%
-----	-----	---------------	----	---	--------------

23. *How does the size of your school's library/resource/media center compare with the size of a typical classroom in your building?*

Smaller:	2	1.55%	About the same size:	17	13.18%	Larger:	110	85.27%
----------	---	--------------	----------------------	----	---------------	---------	-----	---------------

24. *How many classrooms would fit in the space used for your library/resource/media center?*

Minimum:	1	Maximum:	3	Median:	2	Average:	3
----------	---	----------	---	---------	---	----------	---

25. *If you have a library/resource/media center, is it staffed by a licensed, professional librarian?*

Yes	114	88.37%	No	15	11.63%
-----	-----	---------------	----	----	---------------

26. *What percent time is your library/resource/media center staffed by a licensed, professional librarian?*

Number of schools reporting library/resource/media center staffed by licensed, professional librarian: **114**

Minimum:	3%	Maximum:	100%	Median:	91%	Average:	70.38%
----------	----	----------	------	---------	-----	----------	--------

CESA: 05 *Number of schools reported for CESA 05: 136*

27. Does this school have a separate room for a parent/family center?

Yes 23 **16.91%** No 113 **83.09%**

28. How does the size of your school's parent/family center compare with the size of a typical classroom in your building?

Smaller: 11 **47.83%** About the same size: 7 **30.43%** Larger: 5 **21.74%**

29. How many classrooms would fit in the space used for the parent/family center?

Minimum: .25 Maximum: 15 Median: 1 Average: 2

B. SCHOOL SAFETY

30. Does your school have a "Locked Door" policy (doors can only be opened from the inside)?

Yes 72 **52.94%** No 64 **47.06%**

31. Does your school have a "Check-In" policy for school visitors?

Yes 133 **97.79%** No 3 **2.21%**

32. Does your school have an established emergency response plan for dealing with school safety issues?

Yes 128 **94.12%** No 8 **5.88%**

33. Does your school have on-site security provided by police officers or private security guards?

Yes 17 **12.50%** No 119 **87.50%**

34. Does your school have parent or other community volunteers to assist in monitoring the school?

Yes 10 **7.35%** No 126 **92.65%**

35. Does your school have metal detectors?

Yes 1 **0.74%** No 135 **99.26%**

36. Does your school have surveillance cameras located within the school building or on school grounds?

Yes 11 **8.09%** No 125 **91.91%**

C. EDUCATIONAL APPROPRIATENESS AND SUITABILITY

ELEMENTARY SCHOOLS ONLY

Number of Elementary Schools Reported: 86

Educational Appropriateness:

38. Size of instructional classrooms are large enough to allow for alternative room arrangements to facilitate curricular objectives.

Strongly agree with statement:	27	27.84%	Disagree with statement:	19	19.59%
Agree with statement:	49	50.52%	Strongly disagree with statement:	2	2.06%

39. Pre-kindergarten and Kindergarten space accommodates developmental range and needs of young children by providing a minimum of 35 square feet per occupant.

Strongly agree with statement:	32	32.99%	Disagree with statement:	15	15.46%
Agree with statement:	46	47.42%	Strongly disagree with statement:	4	4.12%

CESA: 05

Number of schools reported for CESA 05: 136

Number of Elementary Schools reported for CESA 05: 86

40. Adequate space is available for small work group instruction (less than 15 students).

Strongly agree with statement:	23	23.71%	Disagree with statement:	22	22.68%
Agree with statement:	45	46.39%	Strongly disagree with statement:	7	7.22%

41. Adequate space is available to allow instructional classrooms to maintain a class size of less than 30 students.

Strongly agree with statement:	29	29.90%	Disagree with statement:	8	8.25%
Agree with statement:	58	59.79%	Strongly disagree with statement:	2	2.06%

42. Adequate space is available for large work group instruction (more than 30 students).

Strongly agree with statement:	14	14.43%	Disagree with statement:	24	24.74%
Agree with statement:	48	49.48%	Strongly disagree with statement:	11	11.34%

43. Equipment and furniture (such as shelving units, tables, and chairs) are the appropriate size for the building's student population.

Strongly agree with statement:	36	37.11%	Disagree with statement:	0	0.00%
Agree with statement:	61	62.89%	Strongly disagree with statement:	0	0.00%

Building Suitability for Education:

44. Buildings materials, color schemes, and decor provide impetus to learning.

Strongly agree with statement:	39	40.21%	Disagree with statement:	3	3.09%
Agree with statement:	55	56.70%	Strongly disagree with statement:	0	0.00%

45. Drinking fountain and restroom facilities are an appropriate height and size for the school building population and conveniently located.

Strongly agree with statement:	27	27.84%	Disagree with statement:	5	5.15%
Agree with statement:	65	67.01%	Strongly disagree with statement:	0	0.00%

46. Student services areas (e.g., counselor and medical) ensure privacy and are of sufficient size.

Strongly agree with statement:	14	14.58%	Disagree with statement:	27	28.13%
Agree with statement:	46	47.92%	Strongly disagree with statement:	9	9.38%

47. Building is accessible to students with disabilities.

Strongly agree with statement:	36	37.50%	Disagree with statement:	9	9.38%
Agree with statement:	45	46.88%	Strongly disagree with statement:	6	6.25%

48. Space is available and appropriate for extended day learning opportunities, including before and after school day care.

Strongly agree with statement:	18	19.15%	Disagree with statement:	25	26.60%
Agree with statement:	49	52.13%	Strongly disagree with statement:	2	2.13%

School Site Suitability:

49. Site is large enough to meet educational needs and is accessible.

Strongly agree with statement:	31	32.63%	Disagree with statement:	13	13.68%
Agree with statement:	47	49.47%	Strongly disagree with statement:	4	4.21%

CESA: 05

Number of schools reported for CESA 05: 136

Number of Elementary Schools reported for CESA 05: 86

50. Site has a safe outdoor space where children can engage in a variety of games, sports, and motor activities.

Strongly agree with statement:	37	38.54%	Disagree with statement:	8	8.33%
Agree with statement:	50	52.08%	Strongly disagree with statement:	1	1.04%

51. Student loading areas are segregated from other vehicular traffic and pedestrian walkways.

Strongly agree with statement:	19	19.79%	Disagree with statement:	34	35.42%
Agree with statement:	30	31.25%	Strongly disagree with statement:	13	13.54%

Playground Site and Equipment Suitability:

52. Playground size is appropriate for number of students.

Strongly agree with statement:	31	32.29%	Disagree with statement:	11	11.46%
Agree with statement:	47	48.96%	Strongly disagree with statement:	7	7.29%

53. Playgrounds are separated from streets and parking areas with fencing or other permanent material.

Strongly agree with statement:	29	30.21%	Disagree with statement:	23	23.96%
Agree with statement:	42	43.75%	Strongly disagree with statement:	2	2.08%

54. Playgrounds are well equipped and appropriate for age levels.

Strongly agree with statement:	23	23.96%	Disagree with statement:	16	16.67%
Agree with statement:	54	56.25%	Strongly disagree with statement:	3	3.13%

55. Playground equipment is accessible to students with disabilities.

Strongly agree with statement:	10	10.42%	Disagree with statement:	39	40.63%
Agree with statement:	44	45.83%	Strongly disagree with statement:	3	3.13%

56. Playground equipment is free of sharp edges, of sound construction, and in good condition.

Strongly agree with statement:	29	30.21%	Disagree with statement:	8	8.33%
Agree with statement:	59	61.46%	Strongly disagree with statement:	0	0.00%

MIDDLE, JUNIOR HIGH, AND HIGH SCHOOLS ONLY

Number of Secondary Schools Reported: 50

Educational Appropriateness:

57. Size of instructional classrooms are large enough to allow for alternative room arrangements to facilitate curricular objectives.

Strongly agree with statement:	14	26.42%	Disagree with statement:	4	7.55%
Agree with statement:	35	66.04%	Strongly disagree with statement:	0	0.00%

58. Size and design of special learning areas (science labs, art, technology education, music and special education) is compatible with instructional need.

Strongly agree with statement:	15	28.30%	Disagree with statement:	11	20.75%
Agree with statement:	26	49.06%	Strongly disagree with statement:	1	1.89%

59. Adequate space is available for small work group instruction (less than 15 students).

Strongly agree with statement:	16	30.19%	Disagree with statement:	10	18.87%
Agree with statement:	26	49.06%	Strongly disagree with statement:	1	1.89%

CESA: 05

Number of schools reported for CESA 05: 136

Number of Secondary Schools reported for CESA 05: 50

60. Adequate space is available to allow instructional classrooms to maintain a class size of less than 30 students.

Strongly agree with statement:	25	47.17%	Disagree with statement:	2	3.77%
Agree with statement:	26	49.06%	Strongly disagree with statement:	0	0.00%

61. Adequate space is available for large work group instruction (more than 30 students).

Strongly agree with statement:	11	20.75%	Disagree with statement:	16	30.19%
Agree with statement:	23	43.40%	Strongly disagree with statement:	3	5.66%

Building Suitability for Education:

62. Buildings materials, color schemes, and decor provide impetus to learning.

Strongly agree with statement:	20	37.74%	Disagree with statement:	5	9.43%
Agree with statement:	28	52.83%	Strongly disagree with statement:	0	0.00%

63. Drinking fountain and restroom facilities are an appropriate height and size for the school building population and conveniently located.

Strongly agree with statement:	28	52.83%	Disagree with statement:	6	11.32%
Agree with statement:	18	33.96%	Strongly disagree with statement:	1	1.89%

64. Student services areas (e.g., counselor and medical) ensure privacy and are of sufficient size.

Strongly agree with statement:	15	28.30%	Disagree with statement:	7	13.21%
Agree with statement:	28	52.83%	Strongly disagree with statement:	3	5.66%

65. Building is accessible to students with disabilities.

Strongly agree with statement:	31	58.49%	Disagree with statement:	4	7.55%
Agree with statement:	15	28.30%	Strongly disagree with statement:	3	5.66%

66. Space is available and appropriate for extended day learning opportunities, including before and after school day care.

Strongly agree with statement:	8	15.09%	Disagree with statement:	18	33.96%
Agree with statement:	25	47.17%	Strongly disagree with statement:	2	3.77%

School Site Suitability:

67. Site is large enough to meet educational needs and is accessible.

Strongly agree with statement:	24	45.28%	Disagree with statement:	2	3.77%
Agree with statement:	23	43.40%	Strongly disagree with statement:	4	7.55%

68. Site has a safe outdoor space where students can engage in a variety of games, sports, and motor activities.

Strongly agree with statement:	24	45.28%	Disagree with statement:	3	5.66%
Agree with statement:	24	45.28%	Strongly disagree with statement:	2	3.77%

69. Student loading areas are segregated from other vehicular traffic and pedestrian walkways.

Strongly agree with statement:	10	18.87%	Disagree with statement:	21	39.62%
Agree with statement:	18	33.96%	Strongly disagree with statement:	4	7.55%

End of Survey
