



CESA: 11 *Number of schools reported for CESA 11: 93*

Which best describes the location of your school building?

0	0.00%	<i>Large Central City (Population greater than 400,000 and density greater than 6,000.)</i>
0	0.00%	<i>Mid-Size Central City (Population less than 400,000 and density less than 6,000.)</i>
20	21.51%	<i>Urban Fringe of Large City (Defined as urban by the Census Bureau.)</i>
0	0.00%	<i>Urban Fringe of Mid-Size City (Defined as urban by the Census Bureau.)</i>
0	0.00%	<i>Large Town (Population greater than or equal to 25,000.)</i>
13	13.98%	<i>Small Town (Population less than 25,000 and greater than or equal to 2,500.)</i>
60	64.52%	<i>Rural (Population less than 2,500 and coded rural by the Census Bureau.)</i>

A. PHYSICAL STRUCTURE AND MECHANICAL FEATURES

4. *When was the school originally constructed?*

<i>Pre-1900</i>	1	1.08%	<i>1930-1939</i>	5	5.38%	<i>1970-1979</i>	6	6.45%
<i>1900-1909</i>	1	1.08%	<i>1940-1949</i>	1	1.08%	<i>1980-1989</i>	3	3.23%
<i>1910-1919</i>	2	2.15%	<i>1950-1959</i>	20	21.51%	<i>1990-1999</i>	19	20.43%
<i>1920-1929</i>	8	8.60%	<i>1960-1969</i>	27	29.03%			

5. *In your opinion, is this school building overcrowded?*

Yes	29	31.18%	No	64	68.82%
-----	----	---------------	----	----	---------------

6. *If the original building has been renovated or had additions, when was the most recent, MAJOR renovation or addition?*

<i>No Renovation</i>	22	23.66%	<i>1940-1949</i>	0	0.00%	<i>1970-1979</i>	8	8.60%
<i>Before 1930</i>	0	0.00%	<i>1950-1959</i>	4	4.30%	<i>1980-1989</i>	7	7.53%
<i>1930-1939</i>	0	0.00%	<i>1960-1969</i>	1	1.08%	<i>1990-1999</i>	51	54.84%

7. *How many total square feet does the original building have?*

<i>Minimum:</i>	2,400	<i>Maximum:</i>	150,000	<i>Median:</i>	47,816	<i>Average:</i>	51,444
-----------------	-------	-----------------	---------	----------------	--------	-----------------	--------

8. *If the building has been renovated or added on to, how many total square feet exist now?*

<i>Minimum:</i>	3,104	<i>Maximum:</i>	280,000	<i>Median:</i>	74,913	<i>Average:</i>	81,352
-----------------	-------	-----------------	---------	----------------	--------	-----------------	--------

9. *How many portable classrooms were in use during the 1998-99 school year?*

Number of schools reporting the use of portable classrooms: 10

<i>Minimum:</i>	1	<i>Maximum:</i>	2	<i>Median:</i>	1	<i>Average:</i>	1
-----------------	---	-----------------	---	----------------	---	-----------------	---

10. *Does the school accommodate any of its students in instructional facilities located OFF-SITE?*

Yes	20	21.51%	No	73	78.49%
-----	----	---------------	----	----	---------------

11. *How many of this school's FTE students are located in OFF-SITE facilities?*

Number of schools reporting OFF-SITE facilities: 20

<i>Minimum:</i>	1	<i>Maximum:</i>	200	<i>Median:</i>	7	<i>Average:</i>	27
-----------------	---	-----------------	-----	----------------	---	-----------------	----

CESA: 11 *Number of schools reported for CESA 11: 93*

Definitions for questions #12 and #15:

Excellent: New or easily restorable to "like new" only minimal routine maintenance.

Good: Only routine maintenance or minor repair required.

Adequate: Some preventive maintenance and/or corrective repair required.

Fair: Fails to meet code and functional requirement in some cases; extensive repair.

Poor: Consistent substandard performance; major corrective repair or overhaul.

Replace: Non-operational or significantly substandard performance. Replacement

NA: Not Applicable

12. *What is the overall condition of the original buildings and the permanent additions?*

	<i>Excellent</i>	<i>Good</i>	<i>Adequate</i>	<i>Fair</i>	<i>Poor</i>	<i>Replace</i>	<i>NA</i>
<i>Original Buildings:</i>	26 27.96%	22 23.66%	27 29.03%	9 9.68%	6 6.45%	2 2.15%	1 1.08%
<i>Permanent Additions:</i>	29 31.18%	21 22.58%	12 12.90%	9 9.68%	3 3.23%	0 0.00%	19 20.43%

13. *What would be the total cost of all repairs/renovations/modernizations required to put this school's ON-SITE buildings in good overall condition?*

Number of schools reporting cost for repairs/renovations/modernizations: 46

CESA Total Costs = \$81,936,000

Minimum: \$15,000 Maximum: \$10,000,000 Median: \$550,000 Average: \$1,781,217

14. *On which of the sources listed below is this estimate based? Choose all that apply.*

- 48 **32.88%** *Does not apply--already in good (or better) overall condition.*
- 22 **15.07%** *Facilities inspection/assessment performed within the last three years by licensed professionals.*
- 11 **7.53%** *Repair/renovation/modernization work already being performed/contracted for.*
- 16 **10.96%** *Capital improvement/facilities master plan or schedule.*
- 32 **21.92%** *My best professional judgement.*
- 17 **11.64%** *Opinions of others.*

15. *Overall, what is the physical condition of each of the building features listed below for this school's ON-SITE buildings?*

	<i>Excellent</i>	<i>Good</i>	<i>Adequate</i>	<i>Fair</i>	<i>Poor</i>	<i>Replace</i>
<i>Roofs:</i>	30 32.26%	27 29.03%	20 21.51%	11 11.83%	3 3.23%	2 2.15%
<i>Framing, floors, foundations:</i>	31 33.33%	44 47.31%	9 9.68%	6 6.45%	3 3.23%	0 0.00%
<i>Exterior walls, finishes, windows, doors:</i>	25 26.88%	30 32.26%	25 26.88%	8 8.60%	5 5.38%	0 0.00%
<i>Interior finishes, trims:</i>	27 29.03%	33 35.48%	19 20.43%	12 12.90%	2 2.15%	0 0.00%
<i>Plumbing:</i>	25 26.88%	37 39.78%	18 19.35%	7 7.53%	6 6.45%	0 0.00%
<i>Heating ventilation, air conditioning:</i>	24 25.81%	28 30.11%	20 21.51%	10 10.75%	11 11.83%	0 0.00%
<i>Electrical power:</i>	33 35.48%	27 29.03%	14 15.05%	15 16.13%	3 3.23%	1 1.08%
<i>Electrical lighting:</i>	34 36.56%	30 32.26%	16 17.20%	8 8.60%	4 4.30%	1 1.08%
<i>Life safety requirements (e.g., emergency lighting and warning systems, exit signs):</i>	39 41.94%	35 37.63%	12 12.90%	4 4.30%	1 1.08%	2 2.15%

CESA: 11 *Number of schools reported for CESA 11: 93*

16. *How adequate is your current maintenance budget for keeping your buildings in good overall condition?*

Very Adequate:	3	3.23%	Somewhat Adequate:	36	38.71%
Adequate:	39	41.94%	Not adequate at all:	15	16.13%

17. *How satisfactory or unsatisfactory is each of the following environmental factors in this school's ON-SITE buildings?*

	Very Satisfactory	Satisfactory	Unsatisfactory	Very Unsatisfactory
Lighting:	33 35.48%	52 55.91%	7 7.53%	1 1.08%
Heating:	27 29.03%	54 58.06%	11 11.83%	1 1.08%
Ventilation:	23 24.73%	49 52.69%	18 19.35%	3 3.23%
Indoor air quality:	28 30.11%	47 50.54%	16 17.20%	2 2.15%
Acoustics for noise control:	26 27.96%	50 53.76%	16 17.20%	1 1.08%
Flexibility of instructional space:	20 21.51%	40 43.01%	24 25.81%	9 9.68%
Energy efficiency/conservation:	20 21.51%	54 58.06%	15 16.13%	4 4.30%
Physical security of buildings:	20 21.51%	52 55.91%	17 18.28%	4 4.30%
Exterior noise:	33 35.48%	55 59.14%	4 4.30%	1 1.08%

18. *How many instructional classrooms were in use as of the third Friday in September, 1998?*

Total number of instructional classrooms reported in use as of the third Friday in September, 1998: **2,431**

Minimum:	10	Maximum:	99	Median:	25	Average:	26
----------	----	----------	----	---------	----	----------	----

19. *Does the school building have CENTRAL air conditioning (cools all interior space)?*

Yes	16	17.20%	No	77	82.80%
-----	----	---------------	----	----	---------------

20. *Does this school have air conditioning in instructional classrooms, computer labs, and/or the library?*

25 **30.86%** Yes, in instructional classrooms.

33 **40.74%** Yes, in computer labs.

23 **28.40%** Yes, in the library.

21. *How many instructional classrooms have air conditioning?*

Minimum:	1	Maximum:	60	Median:	4	Average:	9
----------	---	----------	----	---------	---	----------	---

22. *Does this school have a separate room for a library/resource/media center?*

Yes	89	95.70%	No	4	4.30%
-----	----	---------------	----	---	--------------

23. *How does the size of your school's library/resource/media center compare with the size of a typical classroom in your building?*

Smaller:	1	1.12%	About the same size:	8	8.99%	Larger:	80	89.89%
----------	---	--------------	----------------------	---	--------------	---------	----	---------------

24. *How many classrooms would fit in the space used for your library/resource/media center?*

Minimum:	1	Maximum:	3	Median:	3	Average:	3
----------	---	----------	---	---------	---	----------	---

25. *If you have a library/resource/media center, is it staffed by a licensed, professional librarian?*

Yes	84	94.38%	No	5	5.62%
-----	----	---------------	----	---	--------------

26. *What percent time is your library/resource/media center staffed by a licensed, professional librarian?*

Number of schools reporting library/resource/media center staffed by licensed, professional librarian: **84**

Minimum:	20%	Maximum:	100%	Median:	100%	Average:	83.15%
----------	-----	----------	------	---------	------	----------	--------

CESA: 11 *Number of schools reported for CESA 11: 93*

27. *Does this school have a separate room for a parent/family center?*

Yes 15 **16.13%** No 78 **83.87%**

28. *How does the size of your school's parent/family center compare with the size of a typical classroom in your building?*

Smaller: 12 **80.00%** About the same size: 2 **13.33%** Larger: 1 **6.67%**

29. *How many classrooms would fit in the space used for the parent/family center?*

Minimum: .33 Maximum: 3 Median: 1 Average: 1

B. SCHOOL SAFETY

30. *Does your school have a "Locked Door" policy (doors can only be opened from the inside)?*

Yes 32 **34.41%** No 61 **65.59%**

31. *Does your school have a "Check-In" policy for school visitors?*

Yes 91 **97.85%** No 2 **2.15%**

32. *Does your school have an established emergency response plan for dealing with school safety issues?*

Yes 85 **91.40%** No 8 **8.60%**

33. *Does your school have on-site security provided by police officers or private security guards?*

Yes 2 **2.15%** No 91 **97.85%**

34. *Does your school have parent or other community volunteers to assist in monitoring the school?*

Yes 10 **10.75%** No 83 **89.25%**

35. *Does your school have metal detectors?*

Yes 0 **0.00%** No 93 **100.00%**

36. *Does your school have surveillance cameras located within the school building or on school grounds?*

Yes 4 **4.30%** No 89 **95.70%**

C. EDUCATIONAL APPROPRIATENESS AND SUITABILITY

ELEMENTARY SCHOOLS ONLY
Educational Appropriateness:

Number of Elementary Schools Reported: 47

38. *Size of instructional classrooms are large enough to allow for alternative room arrangements to facilitate curricular objectives.*

Strongly agree with statement: 12 **19.35%** Disagree with statement: 14 **22.58%**
Agree with statement: 33 **53.23%** Strongly disagree with statement: 3 **4.84%**

39. *Pre-kindergarten and Kindergarten space accommodates developmental range and needs of young children by providing a minimum of 35 square feet per occupant.*

Strongly agree with statement: 19 **30.65%** Disagree with statement: 9 **14.52%**
Agree with statement: 29 **46.77%** Strongly disagree with statement: 5 **8.06%**

CESA: 11

Number of schools reported for CESA 11: 93

Number of Elementary Schools reported for CESA 11: 47

40. Adequate space is available for small work group instruction (less than 15 students).

Strongly agree with statement:	15	24.19%	Disagree with statement:	19	30.65%
Agree with statement:	24	38.71%	Strongly disagree with statement:	4	6.45%

41. Adequate space is available to allow instructional classrooms to maintain a class size of less than 30 students.

Strongly agree with statement:	22	35.48%	Disagree with statement:	10	16.13%
Agree with statement:	29	46.77%	Strongly disagree with statement:	1	1.61%

42. Adequate space is available for large work group instruction (more than 30 students).

Strongly agree with statement:	11	17.74%	Disagree with statement:	28	45.16%
Agree with statement:	12	19.35%	Strongly disagree with statement:	11	17.74%

43. Equipment and furniture (such as shelving units, tables, and chairs) are the appropriate size for the building's student population.

Strongly agree with statement:	26	41.94%	Disagree with statement:	6	9.68%
Agree with statement:	29	46.77%	Strongly disagree with statement:	1	1.61%

Building Suitability for Education:

44. Buildings materials, color schemes, and decor provide impetus to learning.

Strongly agree with statement:	24	38.71%	Disagree with statement:	9	14.52%
Agree with statement:	29	46.77%	Strongly disagree with statement:	0	0.00%

45. Drinking fountain and restroom facilities are an appropriate height and size for the school building population and conveniently located.

Strongly agree with statement:	24	38.71%	Disagree with statement:	10	16.13%
Agree with statement:	28	45.16%	Strongly disagree with statement:	0	0.00%

46. Student services areas (e.g., counselor and medical) ensure privacy and are of sufficient size.

Strongly agree with statement:	19	30.65%	Disagree with statement:	15	24.19%
Agree with statement:	22	35.48%	Strongly disagree with statement:	6	9.68%

47. Building is accessible to students with disabilities.

Strongly agree with statement:	27	43.55%	Disagree with statement:	11	17.74%
Agree with statement:	19	30.65%	Strongly disagree with statement:	5	8.06%

48. Space is available and appropriate for extended day learning opportunities, including before and after school day care.

Strongly agree with statement:	13	22.03%	Disagree with statement:	17	28.81%
Agree with statement:	25	42.37%	Strongly disagree with statement:	4	6.78%

School Site Suitability:

49. Site is large enough to meet educational needs and is accessible.

Strongly agree with statement:	24	40.00%	Disagree with statement:	8	13.33%
Agree with statement:	24	40.00%	Strongly disagree with statement:	4	6.67%

CESA: 11

Number of schools reported for CESA 11: 93

Number of Elementary Schools reported for CESA 11: 47

50. Site has a safe outdoor space where children can engage in a variety of games, sports, and motor activities.

Strongly agree with statement:	29	46.77%	Disagree with statement:	6	9.68%
Agree with statement:	26	41.94%	Strongly disagree with statement:	1	1.61%

51. Student loading areas are segregated from other vehicular traffic and pedestrian walkways.

Strongly agree with statement:	12	19.35%	Disagree with statement:	17	27.42%
Agree with statement:	24	38.71%	Strongly disagree with statement:	9	14.52%

Playground Site and Equipment Suitability:

52. Playground size is appropriate for number of students.

Strongly agree with statement:	26	41.94%	Disagree with statement:	6	9.68%
Agree with statement:	27	43.55%	Strongly disagree with statement:	3	4.84%

53. Playgrounds are separated from streets and parking areas with fencing or other permanent material.

Strongly agree with statement:	27	43.55%	Disagree with statement:	14	22.58%
Agree with statement:	20	32.26%	Strongly disagree with statement:	1	1.61%

54. Playgrounds are well equipped and appropriate for age levels.

Strongly agree with statement:	18	29.03%	Disagree with statement:	12	19.35%
Agree with statement:	30	48.39%	Strongly disagree with statement:	2	3.23%

55. Playground equipment is accessible to students with disabilities.

Strongly agree with statement:	18	29.03%	Disagree with statement:	20	32.26%
Agree with statement:	22	35.48%	Strongly disagree with statement:	2	3.23%

56. Playground equipment is free of sharp edges, of sound construction, and in good condition.

Strongly agree with statement:	24	38.71%	Disagree with statement:	3	4.84%
Agree with statement:	34	54.84%	Strongly disagree with statement:	1	1.61%

MIDDLE, JUNIOR HIGH, AND HIGH SCHOOLS ONLY

Number of Secondary Schools Reported: 46

Educational Appropriateness:

57. Size of instructional classrooms are large enough to allow for alternative room arrangements to facilitate curricular objectives.

Strongly agree with statement:	7	14.58%	Disagree with statement:	9	18.75%
Agree with statement:	31	64.58%	Strongly disagree with statement:	1	2.08%

58. Size and design of special learning areas (science labs, art, technology education, music and special education) is compatible with instructional need.

Strongly agree with statement:	12	25.00%	Disagree with statement:	8	16.67%
Agree with statement:	23	47.92%	Strongly disagree with statement:	5	10.42%

59. Adequate space is available for small work group instruction (less than 15 students).

Strongly agree with statement:	11	22.92%	Disagree with statement:	11	22.92%
Agree with statement:	24	50.00%	Strongly disagree with statement:	2	4.17%

CESA: 11

Number of schools reported for CESA 11: 93

Number of Secondary Schools reported for CESA 11: 46

60. Adequate space is available to allow instructional classrooms to maintain a class size of less than 30 students.

Strongly agree with statement:	19	39.58%	Disagree with statement:	2	4.17%
Agree with statement:	25	52.08%	Strongly disagree with statement:	2	4.17%

61. Adequate space is available for large work group instruction (more than 30 students).

Strongly agree with statement:	9	18.75%	Disagree with statement:	19	39.58%
Agree with statement:	13	27.08%	Strongly disagree with statement:	7	14.58%

Building Suitability for Education:

62. Buildings materials, color schemes, and decor provide impetus to learning.

Strongly agree with statement:	19	39.58%	Disagree with statement:	7	14.58%
Agree with statement:	21	43.75%	Strongly disagree with statement:	1	2.08%

63. Drinking fountain and restroom facilities are an appropriate height and size for the school building population and conveniently located.

Strongly agree with statement:	18	37.50%	Disagree with statement:	6	12.50%
Agree with statement:	24	50.00%	Strongly disagree with statement:	0	0.00%

64. Student services areas (e.g., counselor and medical) ensure privacy and are of sufficient size.

Strongly agree with statement:	14	29.17%	Disagree with statement:	12	25.00%
Agree with statement:	19	39.58%	Strongly disagree with statement:	3	6.25%

65. Building is accessible to students with disabilities.

Strongly agree with statement:	22	45.83%	Disagree with statement:	6	12.50%
Agree with statement:	18	37.50%	Strongly disagree with statement:	2	4.17%

66. Space is available and appropriate for extended day learning opportunities, including before and after school day care.

Strongly agree with statement:	11	22.92%	Disagree with statement:	9	18.75%
Agree with statement:	24	50.00%	Strongly disagree with statement:	4	8.33%

School Site Suitability:

67. Site is large enough to meet educational needs and is accessible.

Strongly agree with statement:	15	31.25%	Disagree with statement:	5	10.42%
Agree with statement:	24	50.00%	Strongly disagree with statement:	4	8.33%

68. Site has a safe outdoor space where students can engage in a variety of games, sports, and motor activities.

Strongly agree with statement:	16	33.33%	Disagree with statement:	3	6.25%
Agree with statement:	25	52.08%	Strongly disagree with statement:	4	8.33%

69. Student loading areas are segregated from other vehicular traffic and pedestrian walkways.

Strongly agree with statement:	6	12.50%	Disagree with statement:	20	41.67%
Agree with statement:	15	31.25%	Strongly disagree with statement:	7	14.58%

End of Survey